RISO, INC.
300 Rosewood Drive, Suite 210, Danvers, MA 01923 Telephone (508) 777-7377 Fax (508) 777-2517

TECHNICAL INFORMATION

TO: Dealer Technical Department

FROM: RISO, Inc. Technical Department

SUBJECT: Image Area

MODEL: 2700, 3500

DATE: 5-11-88

ISSUE # 23

The new 2700 image scanner without glass and the new machine model 3500 image scanner, reduces the image from side to side approximately 3mm. This reduction is approximately 1.5mm on each side of the copy. We are confident that the slight reduction in the image width will not be a problem within the applications typically produced on the equipment.

The reason for the slight image reduction, side to side, is the change made by the manufacturer of the facsimile component going from 16 dots/mm to the current high resolution 400 dots/inch.